NTSB ID: IAD05RA127 Aircraft Registration Number: OB-1809-P

Occurrence Date: 08/23/2005 Most Critical Injury: Fatal

Occurrence Type: Accident Investigated By:

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Pucalipa			2010	UTC	
Airport Proximity:	Distance Fror	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

- morale membalish out many									
Aircraft Manufacturer	Model/Series	Type of Aircraft							
Boeing	737-200	Airplane							

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 23, 2005, about 2010 universal coordinated time (1510 local time), a Boeing 737-200, Peruvian registry OB-1809-P, operating as Aerolinea Transportes Aereos Nacionales de Selva (TANS) Peru flight 204, was destroyed when it impacted trees and swampy terrain while approaching Captain FAP David Abenzur Rengifo Airport (PCL), Pucallpa, Peru. The captain, first officer, 2 flight attendants and 40 passengers were fatally injured. One additional passenger was missing and presumed fatally injured. Two flight attendants were seriously injured, and 53 passengers incurred minor to serious injuries. Instrument meteorological conditions prevailed, and the flight was operating on an instrument flight rules flight plan from Jorge Chavez International Airport (LIM), Lima, Peru, to Pucallpa. The scheduled passenger flight was conducted under Peruvian flight regulations.

The accident occurred during a thunderstorm, in daylight hours, about 2.5 nautical miles south of runway 02, in the vicinity of 8 degrees, 25.0 minutes south latitude, 74 degrees 35.75 minutes west longitude.

The accident is under the jurisdiction of the government of the Republic of Peru. Further information may be obtained from:

Comision de Investigacion de Accidentes de Aviacion (CIAA) Director General de Aviacion Civil Ministerio de Transportes y Comunicaciones Avenida 28 de Julio #800 Lima-1, Peru

Tel: (511) 433-2388

This report is for informational purposes only, and contains only information released by, or obtained from the government of the Republic of Peru.

NTSB ID: IAD05RA127

Occurrence Date: 08/23/2005

				20,20,2000								
AVIATION Occurre				rence Type: Accident								
Landing Facility/Approach In	formation											
Airport Name Airp				Airport Eleva Ft.	tion MSL				Runway Length		Runw	vay Width
Runway Surface Type:												
Runway Surface Condition:												
Type Instrument Approach:												
VFR Approach/Landing:												
Aircraft Information												
Aircraft Manufacturer Boeing			Model. 737-2	/Series 200					Serial	Numbe	er	
Airworthiness Certificate(s):									_			
Landing Gear Type:												
Homebuilt Aircraft? No	Number of Seats:		Certifie	d Max Gross W	LBS Numbe			er of Engines:		:		
Engine Type:			Engine Ma	Engine Manufacturer: Model/Series:						Rated Power:		
- Aircraft Inspection Information												
Type of Last Inspection			Date of Las	Date of Last Inspection Time Sir			nce Last Inspection Hours			Airfran	Airframe Total Time Hours	
- Emergency Locator Transmitter (ELT) Information	<u> </u>										
ELT Installed?	ELT Operate	ed?			ELT A	Aided ii	n Locating Ac	cident S	ite?			
Owner/Operator Information												
Registered Aircraft Owner Street Address												
			City								е	Zip Code
Operator of Aircraft	Operator of Aircraft Street Address											
Transportes Aereos de Selva (TANS) Peru				City Lima							е	Zip Code
Operator Does Business As: Operator Designator Code:												
- Type of U.S. Certificate(s) Held: N	Vone											
Air Carrier Operating Certificate(s)	:											
Operating Certificate: Operator Certificate:												
Regulation Flight Conducted Under: Non-U.S., Commercial												
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only												
	I	FACTU	AL REPO	RT - AVIATI	ON							Page 2

NTSB ID: IAD05RA127

Occurrence Date: 08/23/2005

AVIAT	ION												
First Pilot Information													
Name	lame City									Stat	e C	Date of Birth	Age
On File													
Sex: Seat Occupie	d:	Prir	ncipal Profes	sion:					Cer	tificate	e Numbe	er: On File	-
Certificate(s):													
Airplane Rating(s):													
Rotorcraft/Glider/LTA:													
Instrument Rating(s):													
Instructor Rating(s):													
Type Rating/Endorsement	for Accident/I	ncident Aircra	ft?			C	Current E	Biennial	Flight R	eview	ı?		
Medical Cert.:	Medic	al Cert. Status	S:					D	ate of La	st Me	edical Ex	am:	
	•												
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night		Actual	Instrument	ent Roll		Rotorcraft	Glider	Lighter Than Air
Total Time													
Pilot In Command(PIC)										\perp			
Instructor										\perp			
Last 90 Days					+					+			
Last 30 Days Last 24 Hours					+					+			
	1				1		ala sur Da		10		100	and Dilet?	
Seatbelt Used?	Shot	ulder Harness	Used?			OXIC	ology Pe	errorme	u?		Sec	cond Pilot?	
Flight Plan/Itinerary													
Type of Flight Plan Filed: I	FR												
Departure Point						State	,	Airport Identifier			Departure Time		Time Zone
Lima						LIN		LIM				итс	
Destination State Airport Identifier													
Same as Accident/Incident Location							PCL						
Type of Clearance:													
Type of Airspace:													
Weather Information													
Source of Briefing:													
Method of Briefing:													
										Page 3			

NTSB ID: IAD05RA127

Occurrence Date: 08/23/2005

Occurrence Type: Accident

	FTYBOR			00110110	, o . , p o.	71001001	10						
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevati	on	WOF D	istance From	Accid	dent Site		Direction From Acc	cident Site	
				Ft.	MSL				NM			Deg. Mag.	
				1 1.	IVIOL								
Sky/Lowes	y/Lowest Cloud Condition: Ft. AGL Con							Condition o	Condition of Light:				
Lowest Ce	iling: Overcast			Ft.	AGL	Visib	oility:		SM	Alti	Altimeter: "H		
Temperatu	ıre: °C [Dew Point:		°C	Wind	Direction	:			nsity Altitude: Ft.			
Wind Spee	ed:	Gusts:			Weath	ner Cond	tions at Accide	ent Si	ite: Instrum	ent C	Conditions		
Visibility (F	RVR): Ft.	Visibility	(RVV)		SM	Intensit	ty of Precipitat	tion:					
Restriction	s to Visibility:	•											
Type of Pro	ecipitation:												
Accident	Information												
Aircraft Da	mage: Destroyed		Airc	raft Fire	e:	Aircraft Explos				losio	sion		
Classificati	ion:												
- Injury Su	mmary Matrix	Fatal	Serious	Mino	r	None	TOTAL						
First Pi	ilot	1					1						
Second	d Pilot	1					1						
Studen	nt Pilot												
Flight I	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin /	Attendants	2	2				4						
Other 0	Crew												
Passer	ngers	41	53			94							
- TOTAL A	ABOARD -	45	55				100						
Other 0	Ground												
- GRANE	O TOTAL -	45	55			100							
					-								

National Transportation Safety Board

NTSB ID: IAD05RA127

Transportation Safety Doard		
FACTUAL REPORT	Occurrence Date: 08/23/2005	
AVIATION	Occurrence Type: Accident	
Administrative Information	ı	
Investigator-In-Charge (IIC)		
Paul R. Cox		
Additional Persons Participating in This Accident/Incide	ent Investigation:	
Christine Soucy		